



PRODUCT NUMBER: 1015280
Hygiene Kit - Impact Sport

Learn more about our products at howardleight.com

>

Learn more about hearing conservation at hearforever.org >



Overview

Reference Number

1015280

Product Type

Hearing Protection

Range

Earmuffs

Brand

Howard Leight by Honeywell

Brand formerly known as

BILSOM

Industry

- Industry • Administration • Agriculture • Army - Defence • ATEX environment
- Automotive and Part Manufacturer • Aviation • Building and Construction • Catering
- Chemical Industries • Energy or Electricity • Fire Protection brigades • Fishing • Food Industries
- Foundry • Glass Industries • Green Spaces • Homeland defense • Industrial Cleaning
- Iron and steel industry • Laboratory • Logistics • Maintenance • Medical and Pharmaceutical
- Metal steel • Mining and Quarrying • Offshore • Paper Industries • Petro-chemical
- Printing Industries • Services • Ship Building • Telecoms • Textile Industries • Transportation
- Utilities • Water treatment • Welding • Wood Industries

Product Use

Hygiene Kit for Impact Sport

Features & Benefits

Feature

Extends performance and lifetime of earmuff Recommended replacement every 6 months with general use, more frequently with general usage Snap-in ear cushions for quick and easy replacement

Benefit

Includes one pair of snap-in ear cushions and one pair of foam earcup inserts for Bilsom Impact Sport Earmuff only.

Technical Description

Earmuff Construction

None

Other Material

PVC foil, PUR-E, Polyester

Dielectric

Yes

Color

Black

Batteries Needed

None

Sound Amplification

No

AM/FM Radio

No

Automatic Shut-Off Function

No

Audio Input Jack

No

Hi-Visibility

No

Certifications



E.C. Declaration of Conformity

EC Category PPE

0

Literature & Documents



PIC SKU - Pictures

<http://www.honeywellsafety.com/assets/0/324/500/51887/17a6c24b93914711977d85f6014da240.jpg>

Maintenance

Life Cycle

Cushions should be replaced periodically to retain maximum attenuation. Use the following as a guideline for replacement of ear cushions and insert foam. General use and wear - Ear cushions and foam inserts should be replaced at least every 6 months. Heavy use or wear in humid/extreme climates - Ear cushions and foam inserts should be replaced at least every 3 months. Cracking or leakage is visible - replace ear cushions and foam inserts immediately.

Packaging

EAN Code

7312550152805